

**Asanté AeroLAN PCMCIA Rev. B Wireless Adapter
Driver CD Ver. 1.1
RELEASE NOTE 12/21/01**

Thank you for purchasing the Asanté AeroLAN PCMCIA Rev. B Wireless adapter. This is the release note for the AeroLAN PCMCIA Wireless adapter CD, version 1.1. These drivers are the latest to be offered for the AeroLAN PCMCIA Wireless adapter (part number 99-00652-07). Version 1.1 of the AeroLAN PCMCIA Wireless adapter CD supersedes all earlier versions of the AeroLAN PCMCIA Wireless adapter driver sets. These drivers can also be used with the AeroLAN PCMCIA Rev A Wireless adapter.

Hardware SUPPORTED (Subassembly P/N):

61-20652-01 (Windows only)

61-20652-10; 61-20652-14; 61-20652-17 (Windows and Macintosh support)

AeroLAN PCMCIA CD Version History:

1.0	April 2001	Original Release
1.1	December 2001	Add Macintosh Support.

PC Driver History:

1.0	April 2001	Original Release
-----	------------	------------------

Macintosh Driver History:

1.1	December 2001	Support for OS 8.x, 9.x, PM1400, PM5300 and Above
-----	---------------	---

SUPPORTED OPERATING SYSTEMS:

This driver set has been tested on the following Operating Systems:

Windows 95

Windows 98

Windows Me

Windows NT 4.0

Windows 2000

Mac OS 8.x

Mac OS 9.x

SPECIAL NOTE:

Please be aware of the following errata concerning the Asante AeroLAN PCMCIA Wireless Rev. B adapter:

1. The Macintosh 2x Installer will support the AeroLAN PCMCIA Wireless adapter on any PowerBook with PC Card Services 2.x, such as Power Mac 1400 and 5300 series laptops.
2. To avoid a system error message, the user will need to install or update the driver before inserting the adapter, or, disable all network activities before inserting the adapter.
3. Users of all other Powerbooks should use the 3.x version of the Asanté Installer.
4. Macintosh users should be sure to switch networking services away from the AeroLAN adapter before ejecting the card.

